

BLACK SHIELD CHECK LIST (as of 18 Aug 67)				Msn Nr <u>BX6729</u>		H-hour <u>18/0115 Z 1015 L</u>		Page 2 of 2	
H-Minus	25X1A ACTION	25X1A	DOI	RESP INDV	TIME DUE (Z)	TIME DUE (L)	TIME DONE (L)	DONE BY (Initials)	
-10:00	Sen [] (Terminal wx fcsts)		B-5	B	17/1515	18/0015	0000	[]	
-9:00	Rcv [] (NO GO wx fcsts)		B-11	B	1615	0115	0028	[]	
-9:00	Giv [] out to Msn Coord		B-23	B	1615	0115	2100	[]	
25X1A	Plot 12Z RODN & [] RAOBs	<u>T DEV</u>		Y	1700	0200	0200	SE	
25X1A -8:00	Send [] (thru L-hr, if reqd)		B-16	B,A	1715	0215	0955	DEB	
	Plot 12Z 30Mb Chart			Y	1800	0300	0300	SE	
	25X1A								
25X1A	<u>WX SCOUT & SPARE</u> Brief tankers & annotate 175's		B-24	C	2005	0505	0525	JY	
25X1A -4:00	Send [] (Terminal wx fcsts)		B-5	C	2115	0615	0613	JY	
-4:00	Send [] Met Watch obs)		B-18	Z	2115	0615	0617	RAH	
-3:50	Update RAOB's & 30 Mb (18Z Data)	<u>T DEV</u>		Z,X	2125	0625	0630	RAH	
25X1A	Brief tankers & annotate 175's		B-24	C	2030	0530	0445	JY	
-3:30	Brief pilots and ops staff		B-20	A	2145	0645	0645	DEB	
25X1A	<u>PRIMARY</u> Brief tankers & annotate 175's		B-24	C	2230	0730	0745	JY	
25X1A -3:00	Rcv [] Amend (GO/NO GO fcsts)		B-11	A	2215	0715	0616	JY	
-3:00	Rcv Letdown Plates from DCO		B-14	A	2215	0715	0715	DEB	
-3:00	Enter fcsts on Letdown Plates		B-14	A,C	2215	0715	0715	DEB	
-2:30	Msn Obsvr to CP; posts data		B-13	X	2245	0745	—	—	
25X1A -2:00	Rcv [] (Wx Scout reports)		B-22	A	2315	0815	0745	DEB	
	RAH GO TO HILL 0830 Get ESSA-2 Pictures ASAP #7565			Z,C	18/0050	0950	0940	RAH	
-1:40	Msn Fcstr to CP; Obsvr to wx stn		B-13	A,X	2335	0835	—	—	
-1:35	Letdown Plate fcsts to pilots (Notify Mission Coordinator)		B-14	A	2340	0840	0855	DEB	
-1:30	Notify DCO (If need to rebrief pilots)		B-20	A	2345	0845	—	—	
-1:10	Rebrief pilots if necessary		B-20	A	18/0005	0905	1000	DEB	
Verify ACQ T's	CARLA & LCL AREA Get [] Pictures ASAP TARGET			C,X		1245 (P) 1430 (C)	didn't have a chance to get these during the mission.		
	25X1A								
L-Plus	Landing time 0623 Z 1523 L								
+0:15	Return Met Watch to wx station		B-13	X	0638	1538	1600	DEB	
+0:15	Start debriefing form		B-15	A	0638	"	1545	DEB	
+0:45	Attend pilot debriefing		B-15	A	0710	1610	1610	DEB	
25X1A	Give [] input to DCOM Coord after debriefing		B-15	A	ASAP	ASAP	1630	DEB	
+24:00	Turn in Msn Wx File to Intell								

BLACK SHIELD CHECK LIST
(As of 18 Aug 67; with tankers)

Page 1 of 2

Mission Nr BX6729Date 18 OCT 67H-hour 0115 Z 1015 LCode Name BLACK SHIELD

25X1A

L-hour 0505 Z 1405 L

Key Personnel		DCOW Personnel		Duty Hours			
Msn Pilot				17/05-2000; 18/05-1700L			
Spare Pil				17/1500-18/0100L			
Chase Pil				18/01-1000L 17/1000-1700L; 18/07-1700L			
Commander				17/10-1700L; 18/07-1700L			
Msn Coord				17/1800-18/0300L			
Msn DCOM				17/03-1000L; 18/03-1100L			
Msn TTFC					25X1A		
H-Minus	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)	
-24:00	Start this check list	B-3	A	17/0115	17/1015	1930	DEB
-24:00	Arrange work schedule	B-4	A	0115	1015	"	DEB
-23:00	Attend Commander's Briefing	B-1	A	0145	1045	0900	DEB
-23:00	Rcv [] (Prelim Ops Data)	B-1	A	0215	1115	0914	DEB
25X1A	Rcv Wx Scout Call Signs			VRBL	VRBL	1440	DEB
	Give Msn Planning Fcst to TTFC		C			REPEATEDLY 0900-1800	DEB
25X1A	Give [] Crews Prelim Brfg	B-2	C	0300	1200		
	Give [] s Prelim Brfg	B-2	C	0400	1300		
	Coordinate Further TTFC Support	B-2	C	0430	1330	1300	DEB
25X1A							
-21:00	Rcv [] (Tmnl fcsts)	B-5	A	0415	1315	1215	DEB
-21:00	Start Met Watch on wall map	B-2	A	0500	1400	1500	DM
-21:00	Rcv [] Mission wx data)	B-6	A	0415	1315	1230	DEB
25X1A							
	Get ESSA-2 Pictures	B-10	X	0300	1200	0855	RAH
25X1A	Ge [] Pictures	B-10	X	0530	1530	MISSED XMSN	
25X1A	Rcv [] (Composite rte data)	B-6	A	Vrbl	Vrbl		
-17:30	Rcv [] mend (Mission wx)	B-6	A	0745	1645	1540	DM
-17:15	Rcv [] (Tmnl fcsts)	B-5	A	0800	1700	1600	DEB
-17:00	Brief pilot and ops staff	B-7	A	0815	1715	1715	DM
	Rcv ALTERNATES FM DCOM						
25X1A -14:00	Rcv [] (Tanker msn wx fcst)	B-9	B	1015	1915	1838	DEB
-14:00	Turn on 984, T63, & 021 TTY's		Y	1200	2100	2055	SE
25X1A	Rcv [] (Final Ops Data)	B-8	B	1330	2230	2218	DEB

BLACK SHIELD CHECK LIST (as of 18 Aug 67)				Msn Nr <u>BX 6729</u>		H-hour <u>17/0115 Z 1015 L</u>		Page 2 of 2	
H-Minus	25X1A ACTION	25X1A	DOI	RESP INDV	TIME DUE (Z)	TIME DUE (L)	TIME DONE (L)	DONE BY (Initials)	
-10:00	Send [] Terminal wx fcsts)		B-5	B	16/1515	17/0015	0015	[]	
-9:00	Rev [] -NO GO wx fcsts)		B-11	B	1615	0115	0115	[]	
-9:00	Giv [] ut to Msn Coord		B-23	B	1615	0115	2100	[]	
25X1A	Plot 12Z RODN & [] RAOBs			Y	1700	0200	0200	SE	
25X1A -8:00	Send [] (thru L-hr, if reqd)		B-16	B,A	1715	0215	0430	JY	
	Plot 12Z 30Mb Chart			Y	1800	0300	0300	SE	
		25X1A 25X1A							
	WX SCOUT & SPARE []								
25X1A	Brief tankers & annotate 175's		B-24	C	2005	0505	0515	JY	
-4:00	Send [] (Terminal wx fcsts)		B-5	C	2115	0615	0610	JY	
-4:00	Send [] Met Watch obs)		B-18	Z	2115	0615	0615	RH	
-3:50	Update RAOB's & 30 Mb (18Z Data)			Z,X	2125	0625	0630	RH	
25X1A	Brief tankers & annotate 175's		B-24	C	2030	0530	0540	JY	
-3:30	Brief pilots and ops staff		B-20	A	2145	0645	0645 ⁵³	DeB	
		25X1A							
	[] PRIMARY								
	Brief tankers & annotate 175's		B-24	C	2230	0730	0815	JY	
25X1A -3:00	Rev [] Amend (GO/NO GO fcsts)		B-11	A	2215	0715	0645	DeB	
-3:00	Rev Letdown Plates from DCO		B-14	A	2215	0715	0730	DeB	
-3:00	Enter fcsts on Letdown Plates		B-14	A,C	2215	0715	Postponed		
-2:30	Msn Obsvr to CP; posts data		B-13	X	2245	0745	24 hrs		
-2:00	Rev [] (Wx Scout reports)		B-22	A	2315	0815	as of 0840L		
25X1A	Get ESSA-2 Pictures ASAP ^{CY OF #7552} ORIG #7553			Z,C	17/0030	0930			
					17/0200	1100			
-1:40	Msn Fcstr to CP; Obsvr to wx stn		B-13	A,X	2335	0835			
-1:35	Letdown Plate fcsts to pilots (Notify Mission Coordinator)		B-14	A	2340	0840			
-1:30	Notify DCOL (If need to rebrief pilots)		B-20	A	2345	0845			
-1:10	Rebrief pilots if necessary		B-20	A	18/0005	0905			
	IF NEEDED FOR RODN FCST, CY OF #6921				0445	1345			
	Get Nimbus Pictures ASAP ORIG #6922			C,X	0600	1500			
L-Plus	Landing time	Z L							
+0:15	Return Met Watch to wx station		B-13	X					
+0:15	Start debriefing form		B-15	A					
+0:45	Attend pilot debriefing		B-15	A					
25X1A	Giv [] input to DCOM Coord after debriefing		B-15	A	ASAP	ASAP			
+24:00	Approved For Release 2002/06/13 : CIA-RDP69B00041R001000010021-4								

BLACK SHIELD CHECK LIST
(As of 18 Aug 67; with tankers)

Page 1 of 2

Mission Nr BX6729Date 17 OCT 67H-hour 0115 Z 1015 L

Code Name _____

25X1A

L-hour 0505 Z 1405 L

Key Personnel	DCOW Personnel	Duty Hours
Msn Pilot		16/06-1500L; 17/05-1700
Spare Pilot		16/1500-17/0100L
Chase Pilot		17/01-1000L
Commander		16/1000-1800L; 17/07-1700L
Msn Coord		16/1800-17/0300L
Msn DCOM		16/03-1000L; 17/03-1100L
Msn TTFC	EMGCY RCVR FCSTR	25X1A

H-Minus		DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-24:00	Start this check list	B-3	A	16/0115	16/1015	0600	DEB
-24:00	Arrange work schedule	B-4	A	0115	1015	0700	DEB
-23:30	Attend Commander's Briefing	B-1	A	0145	1045	—	—
-23:00	Rcv [] (Prelim Ops Data) 25X1A	B-1	A	0215	1115	0230	JY
	Rcv Wx SCOUT CALL SIGNS			VRBL	VRBL		
	Give Msn Planning Fcst to TTFC		C			—	
25X1A	Give [] Crews Prelim Brfg	B-2	C	0300	1200	—	
25X1A	Give [] Crews Prelim Brfg	B-2	C	0400	1300	—	
	Coordinate Further TTFC Support	B-2	C	0430	1330	—	
25X1A							
-21:00	Rcv [] (Tmnl fcsts)	B-5	A	0415	1315	1232	DEB
21:00	Start Met Watch on wall map	B-2	A	0500	1400	—	
-21:00	Rcv [] (Mission wx data) 25X1A	B-6	A	0415	1315	1232	DEB
	DEALID PAPER & DIAZACHROME CY #7539 Get ESSA-2 Pictures ORIG R CY #7540	B-10	X	0140 0300	1040 1200	1030	RAH
25X1A	Get [] Pictures #6908	B-10	X	0530	1430		
25X1A	Rcv [] (Composite rte data)	B-6	A	Vrbl	Vrbl	1320	DEB
-17:30	Rcv [] (Mission wx)	B-6	A	0745	1645	1604	DEB
-17:15	Rcv [] (Tmnl fcsts)	B-5	A	0800	1700	1621	DEB
-17:00	Brief pilot and ops staff	B-7	A	0815	1715	1715	DEB
-17:00	REV PRIMARY ALTERNATES FM DCOM			0815	1715		
-14:00	Rcv [] (Tanker msn wx fcst) 25X1A	B-9	B	1015	1915	1820	SE
14:00	Turn on 984, T63, & 021 TTY's		Y	1200	2100	2100	SE
25X1A	Rcv [] (Final Ops Data)	B-8	B	1330	2230	2330	DEB

BLACK SHIELD CHECK LIST

(As of 18 Aug 67; with tankers)

Page 1 of 2

Mission Nr BX6729H-hour 0115 Z 1015 LCode Name BLACK SHIELD

25X1A

L-hour 0505 Z 1405 L

Key Personnel	25X1A	DCOW Personnel	Duty Hours
Msn Pilot		A Fcst	15/08-1500L; 16/05-1700
Spare Pilot		B Fcst	15/1500-16/0100L
Chase Pilot		C Fcst	16/01-1000L
Commander		X Obsv	16/07-1700L
Msn Coord		Y Obsv	15/1800-16/0300L
Msn DCOM		Z Obsv	16/03-1100L
Msn TTFC		EMGCY Rcvry Fcstr	25X1A

H-Minus		DOI	RESP INDV	TIME DUE (Z)	TIME DUE (L)	TIME DONE (L)	DONE BY (Initials)
-24:00	Start this check list	B-3	A	15/0115	15/1015	1300	DEB
-24:00	Arrange work schedule	B-4	A	0115	1015	1330	DEB
-23:00	Attend Commander's Briefing	B-1	A	0145	1230 1045	1235	DEB
-23:00	25X1A (Prelim Ops Data)	B-1	A	0215	1115	0405	JY
25X1A	Rcv [] call signs			vrbl	vrbl	1327	DEB
	Give Msn Planning Fcst to TTFC		C	0400	1300	N/R	
25X1A	Give [] Crews Prelim Brfg	B-2	C	0300	1200	N/R	
25X1A	Give [] Crews Prelim Brfg	B-2	C	0400	1300	N/R	
	Coordinate Further TTFC Support	B-2	C	0600 0430	1500 1330	1230	DEB
25X1A	25X1A						
-21:00	Rcv [] (Tmnl fcsts)	B-5	A	0415	1315	1228	DEB
-21:00	Start Met Watch on wall map	B-2	A	0600 0415	1500 1315		
-21:00	Rcv [] (Mission wx data)	B-6	A	0415	1315	1235	DEB
	Get ESSA-2 Pictures	B-10	X	0300	1200	0930	APH
25X1A	Get 25X1A Pictures	B-10	X	0530	1530		
	Rcv [] (Composite rte data)	B-6	A	Vrbl	Vrbl	1825	DEB
-17:30	Rcv [] (Mission wx)	B-6	A	0745	1645	1551	DEB
-17:15	Rcv [] (Tmnl fcsts)	B-5	A	0800	1700	1551	DEB
-17:00	Brief pilot and ops staff	B-7	A	1815	1715	1630	DEB
	25X1A						
-14:00	Rcv [] (Tanker msn wx fcst)	B-9	B	1015	1915	1823	DEB
-14:00	Turn on 984, T63, & 021 TTY's		Y	1200	2100	2050	SE
25X1A	Rcv [] (Final Ops Data)	B-8	B	1330	2230	2245	DEB

BLACK SHIELD CHECK LIST (as of 18 Aug 67)			Msn Nr <u>8X6729</u>		H-hour <u>16/0115 Z 1015 L</u>		Page 2 of 2	
H-Minus	25X1A ACTION	25X1A	DOI	RESP INDV.	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-10:00	Send [] Terminal wx fcsts)	[]	B-5	B	15/1515	16/0015	2335	[]
-9:00	Rcv [] -NO GO wx fcsts)	[]	B-11	B	1615	0115	0032	[]
-9:00	Give [] ut to Msn Coord	[]	B-23	B	1615	0115	2330	[]
25X1A	Plot 12Z RODN & [] RAOBs	[]		Y	1700	0200	Mission postponed	
-8:00	Send [] (thru L-hr, if reqd)	[]	B-16	B,A	1715	0215	24 hours.	
25X1A	Plot 12Z 30Mb Chart	[]		Y	1800	0300	Notified 0220L	
	25X1A							
25X1A	WX SCOUTS SPARE []							
	Brief tankers & annotate 175's	[]	B-24	C	2005	0505		
-4:00	Send [] (Terminal wx fcsts)	[]	B-5	C	2115	0615		
-4:00	Send [] Met Watch obs)	[]	B-18	Z	2115	0615		
-3:50	Update RAOB's & 30 Mb (18Z Data)	[]		Z,X	2125	0625		
25X1A	Brief tankers & annotate 175's	[]	B-24	C	2030	0530		
-3:30	Brief pilots and ops staff	[]	B-20	A	2145	0645		
	TOP OFF							
25X1A	Brief tankers & annotate 175's	[]	B-24	C	2230	0730		
-3:00	Rcv [] Amend (GO/NO GO fcsts)	[]	B-11	A	2215	0715		
-3:00	Rcv Letdown Plates from DCO	[]	B-14	A	2215	0715		
-3:00	Enter fcsts on Letdown Plates	[]	B-14	A,C	2215	0715		
-2:30	Msn Obsvr to CP; posts data	[]	B-13	X	2245	0745		
25X1A	Rcv [] (Wx Scout reports)	[]	B-22	A	2315	0815		
	Get ESSA-2 Pictures ASAP (#7539) FOR SURE HIT	[]		Z,C	0000	0900		
		[]			0115	1015		
-1:40	Msn Fcstr to CP; Obsvr to wx stn	[]	B-13	A,X	2335	0835		
-1:35	Letdown Plate fcsts to pilots (Notify Mission Coordinator)	[]	B-14	A	2340	0840		
-1:30	Notify DCOL (If need to rebrief pilots)	[]	B-20	A	2345	0845		
-1:10	Rebrief pilots if necessary	[]	B-20	A	16/0005	0905		
25X1A	Get [] pictures ASAP (#6908)	[]		C,X	0530	1430		
	L-Plus							
+0:15	Return Met Watch to wx station	[]	B-13	X				
+0:15	Start debriefing form	[]	B-15	A				
+0:45	Attend pilot debriefing	[]	B-15	A				
25X1A	Give [] input to DCOM Coord	[]						
ASAP	after debriefing	[]	B-15	A	ASAP	ASAP		
+24:00	Turn in Msn Wx File to Intell	[]	B-17	A				